# ANALYSIS OF CORROSION OF AIRCRAFT FLUID PRESSURE LINES USING EDDY CURRENT

Dinusha Rangana Edirisinghe

118554 A



Department of Materials Science and Engineering

University of Moratuwa Sri Lanka

# ANALYSIS OF CORROSION OF AIRCRAFT FLUID PRESSURE LINES USING EDDY CURRENT

Edirisinghe Pathiranage Dinusha Rangana Edirisinghe

#### 118554 A



Department of Materials Science and Engineering

University of Moratuwa Sri Lanka

#### **Declaration**

I declare that this is my own work and this thesis does not incorporate without acknowledgement any material previously submitted for a Degree or Diploma in any other University or institute of higher learning and to the best of my knowledge and belief it does not contain any material previously published or written by another person except where the acknowledgement is made in the text.

Also, I hereby grant to University of Moratuwa the non-exclusive right to reproduce and distribute my thesis/dissertation, in whole or in part in print, electronic or other medium. I retain the right to use this content in whole or part in future works (such as articles or books).

Signature:	Date:
	research for the partial fulfillment of the part
Name of the supervisor:	
Signature of the Supervisor:	Date:

#### Acknowledgement

I owe a debt of gratitude to my supervisor, Mr V Sivahar, Senior Lecturer at the Department of Materials Science and Engineering, University of Moratuwa for the vision and foresight which inspired me to conceive this project. I am particularly in debited to my wife and parents for inspiring me to this work; this research work would not have been possible without the great assistance given by them. I further offer my sincere gratitude to the Head of the Department, lecturers and lab assistants of Department of Materials Science and Engineering of University of Moratuwa. I am also priviledged to offer my gratitude to the Head of the Department of Department of Aeronautical Engineering, the library staff at the Kotelawala Defence University and the Commanding Officers, Officers Commanding Maintenance of No.1 Flying Training Wing and No.10 Kfir Squadron of Sri Lanka Air Force for assisting me in numerous ways to make this research a success. Last but by no means least I wish to express my great gratitude to the Commander of the Air force, Commanding Officer, Engineering Officers and laboratory staff of Aircraft Engineering Wing, Usti Venskay Air Proceat Base, Saturayake for supporting me providing wailable esporces. Theses & Dissertations www.lib.mrt.ac.lk

#### **Abstract**

The metal tubes are often used in aircraft to convey fluids to one or more destinations as they are capable of withstanding high levels of internal pressure and hoop stresses. The internal surfaces of fluid carrying metal tubes are frequently corroded once the inner walls are contacted with stagnated fluid for a long period of time. Once corroded, the fluid lines are to be replaced as they become unairworthy. The detection is difficult as there is no method developed for the corrosion detection of small diameter Aluminium metal tubes. This study is to carry out eddy current inspections on small diameter metal tubes and to carry out a qualitative analyze on eddy current impedance plane displays, building up a relationship on the resultant signals. It is also to distinguish the different characteristics of impedance plane displays of internal corrosion and crack signals. A qualitative analysis is the objective in this study as detection of corrosion is the prime objective for the aircraft fluid pressure lines. Since, neither the aircraft manufacturer nor pressure lines manufacturer has given any tolerances for corrosion, irrespective of the depth and the spread of corrosion, the fluid lines are to be replaced with new lines, if the corrosion is detected. Therefore, this study is limited only for a qualitative analysis and will be an eye opener for another study for a quantitative analysis.

Key Words: Hoop stress, eddy current, impedance plane display, unairworthy, quantitative analysis



### TABLE OF CONTENTS

Decl	aration		i
Ackı	nowledge	ement	ii
Abst	ract		iii
Tabl	e of cont	tent	iv
List	of Figure	es	vii
List	of tables	s	viii
List	of abbre	viations	ix
1.	Introd	duction	1
	1.1	General	1
	1.2	Objectives	2
2.	Litera	ature Survey	3
	2.1	The eddy current testing technique	4
	2.2	Applications of eddy current testing	7
	2.3	Different industrial techniques used for inspection of tubes	7
		2.3.1 University enterly nature at Early and an Art	8
	The state of the s	33.2 Electronica Theses, & Dissertations	9
	and the same of th	2.3.3 Saturated Low Frequency Eddy Current Testing (SLOF	EC) 10
		2.3.4 Magnetic Biased Eddy Current Testing (MBEC)	11
	2.4	Eddy current nondestructive testing device using an oscillas	cope to
	identi	ify and locate irregularities in a test piece	12
	2.5	The metal tube testing using ID probes	14
		2.5.1 Eddy current system for testing tubes for defects, eccen	tricity
		and wall thickness	
		2.5.2 Selection of frequency for eddy current tube testing	17
3.	Meth	odology	18
	3.1	Chemical analysis to check the material composition	18
	3.2	Sample preparation	18
	3.3	Preparation of an eddy current probe for smaller diameters	20
		3.3.1 The standard depth of penetration of eddy current probe	22
		3.3.2 Materials used to fabricate the probe	22

		3.3.2.1 Graphite rod	23
		3.3.2.2 Copper wire	23
		3.3.2.3 Capacitor	23
		3.3.2.4 Outer sleeve	23
		3.3.3 Probe specifications	23
	3.4	Detection of internal cracks using eddy current probe	24
	3.5	Samples preparation for microscopic examination	24
	3.6	Conductivity test to find the material conductivity	25
4.	Result	s	26
	4.1	Eddy current signals of each sample	26
	4.2	Microscopic examination test results	27
	4.3	Signal of the crack appeared in impedance plane display	29
	4.4	Materials conductivity test results	29
5.	Discus	ssion	31
	5.1	Detection of corrosion	31
	5.2	Possible reasons for the internal corrosion	32
		University of Moratuwa, Sri Lanka.  5.2.1 Accumulation of moisture Electronic Theses & Dissertations  2.2.2 Erosion of metal due to flowing of fluid through lines  www.lib.mrt.ac.lk	32 32
		5.2.3 Stagnation of fluid in the lines over a period of <b>time</b>	33
		5.2.4 Stress corrosion cracking due to residual stresses	33
	5.3	Difficulties faced during the test and compensation of errors	34
		5.3.1 The study was limited to a qualitative analysis	34
		5.3.2 Eddy current signal is affected by other factors	35
	5.4	Corrosion and over aging	37
6.	Recon	nmendations	39
	6.1	Control of storage conditions of metal fluid lines	39
	6.2	Proper and careful inspection of metal fluid lines	39
	6.3	Usage of appropriate tools for work hardening and carrying	out
	anneal	ling to remove residual stresses	40
	6.4	Use of same material for the replacement of fluid lines	40
	6.5	A method to conduct an external surface inspection to detect	the
	interna	al defects	40

7.	Conclusions	42
Refere	nce List	43



## LIST OF FIGURES

Figure 2.1: The decreasing eddy current density from outer surface	5
Figure 2.2: Relative Effect of Frequency, Conductivity, and Permeability on the Depth of Penetration for a Typical Single-Coil ET Probe	
Figure 2.3: Eddy Current Testing Standard Depth of Penetration for Assorted Materials of Varying Conductivity as a Function of Frequency	
Figure 2.4: Principle of Remote Field Eddy Current technique	.9
Figure 2.5: Operating principle of PET	0
Figure 2.6: Principle of Saturated Low Frequency Eddy Current technique	11
Figure 2.7: Principle of the magnetic biased eddy current technique	12
Figure 2.8: Various display patterns obtained with the designed device f irregularities in a test specimen.	
Figure 2.9: Graphical construction of the figure eight display pattern obtained with device	
Figure 2.10: The principle of an internal diameter probe	15
Figure 3.1: Samples prepared for eddy current inspection	20
Figure 3.2 Pasec 2D eddy current testing machine 2	20
Figure 3.2 Charactery of Moratuwa. Sri Lanka.  Electronic Theses & Dissertations  Figure 3.3 The arrangement of an existing ID probe available in the market	21
Figure 3.4: Fabricated ID Eddy current probe	21
Figure 3.5: Samples prepared for microscopic examination	24
Figure 4.1: Eddy current signal of sample No.1 for Corroded and non-corrode	ed
areas2	26
Figure 4.2: Eddy current signal of sample No.2 for Corroded and non-corrode	ed
areas2	27
Figure 4.3: Eddy current signal of sample No.3 for Corroded and non-corrode	ed
areas2	27
Figure 4.4: Microstructure of corroded area of Sample No.1	28
Figure 4.5: Microstructure of corroded area of Sample No.2	28
Figure 4.6: Microstructure of corroded area of Sample No.3	28
Figure 4.7: Comparison of crack signal and corrosion signal	29
Figure 4.8: Material conductivity test results	30

# LIST OF TABLES

Table 3.1: Material composition of aircraft fluid pressure line sample	18
Table 3.2: Different periods of exposure for samples to 4M NaCl solution	19
Table 3.3: Materials used to fabricate the ID probes	22
Table 3.4: Probe Specifications	23



### LIST OF ABBREVIATIONS

Abbreviation	Description
SLAF	Sri Lanka Air Force
ID	Internal Diameter
NDT	Non Destructive Testing
NDI	Non Destructive Inspection
DBTT	Ductile to Brittle Transition Temperature
AC	Alternating Current
DC	Direct Current
ILI	In Line Inspection
MFL	Magnetic Flux Leakage
RFET	Remote Field Eddy Current Technique
PET	Pulsed Eddy Current Testing
SLOFEC	Saturated Low Frequency Eddy Current
PT-6	Primary Trainer-6
IACS	Unimersity of Moeatuwapp Srislandka. Electronic Theses & Dissertations www.lib.mrt.ac.lk